



NUMBER: 24-001-07

GROUP: Heating and Air Conditioning

DATE: January 20, 2007

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

THIS BULLETIN IS BEING PROVIDED IN ADVANCE. DO NOT ORDER PARTS OR PERFORM ANY ACTIONS RELATED TO THIS BULLETIN UNTIL FEBRUARY 5, 2007.

SUBJECT:

HVAC Floor Air Distribution

OVERVIEW:

This bulletin involves enlarging the HVAC air outlet openings and installing a grille over each opening for the driver and front passenger floor areas.

MODELS:

2005 - 2006	(WH)	Grand Cherokee (International Markets)
2005 - 2006	(WK)	Grand Cherokee
2006	(XH)	Commander (International Markets)
2006	(XK)	Commander

SYMPTOM/CONDITION:

The vehicle operator is concerned with air being directed too strongly on the feet of the driver and front seat passenger.

DIAGNOSIS:

If the vehicle operator describes the Symptom/Condition, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	68028883AA	Grille Package, Floor Outlet

SPECIAL TOOLS/EQUIPMENT REQUIRED:

NPN	Rotary File or Sharp Knife
-----	----------------------------

REPAIR PROCEDURE:

1. Use the template in Grille Package, p/n 68028883AA, to mark the revised opening on the side of front center console.
2. Use a rotary grinder or sharp knife to trim the opening to the marks made in step 1.
3. Snap the appropriate grille from Grille Package, p/n 68028883AA, into the revised opening.



Stick with the Specialists™

4. Repeat steps 1 - 3 for the other side of the console.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
24-65-57-90	Install Floor Outlet Grilles (B)	0.5 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------