

GROUP: Electrical

DATE: March 23,2005

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retreival system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

THIS BULLETIN IS BEING PROVIDED IN ADVANCE. DO NOT ORDER PARTS OR PERFORM ANY ACTIONS RELATED TO THIS BULLETIN UNTIL APRIL 4, 2005.

SUBJECT:

Customer Would Prefer A Louder Warning Tone From The Park Assist System

OVERVIEW:

This bulletin involves replacing the park assist display assembly.

MODELS:

2005	(CS)	Pacifica
2005	(LX)	300
2005	(RS)	Town and Country/Caravan
2005	(RG)	Chrysler Voyager (International Markets)
2005	(WK)	Grand Chrokee

NOTE: This bulletin applies to vehicles equipped with sales code XAA.

SYMPTOM/CONDITION:

Customer states they would prefer that the park assist display audible warning tone be louder.

DIAGNOSIS:

If customer describes the condition, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	56046042AA	Display Assy, Parking Assist

REPAIR PROCEDURE:

 Use the procedures outlined in TechCONNECT, under: Service Info tab, 8 - Electrical / Chime/Buzzer / Park Assist Display to replace the park assist display, p/n 56046042AA.



POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
08-20-05-91	Replace Park Assist Display	0.3 Hrs.

FAILURE CODE:

58	Internal Defect