

NUMBER: 24-009-08

GROUP: Heating & A/C

DATE: November 26, 2008

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retreival system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

SUBJECT:

Warm Air From Instrument Panel Outlets When Cold Air Is Selected

OVERVIEW:

This bulletin involves installing a revised HVAC distribution housing.

MODELS:

2009 (WK) Grand Cherokee 2009 (XK) Commander

NOTE: This bulletin applies to vehicles equipped with Manual Temperature Control built between August 11, 2008 (MDH 0811XX) and October 14, 2008 (1007XX).

SYMPTOM/CONDITION:

The MTC system will not distribute cold air when the control head temperature knob is rotated from full hot to full cold position with blower on high and in panel mode.

DIAGNOSIS:

If a customer indicates that the condition is present, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	68020233AB	Housing, HVAC Distribution - Left Hand Drive - Gas Engine Equipped
1	68020246AB	Housing, HVAC Distribution - Left Hand Drive - Diesel Engine Equipped

REPAIR PROCEDURE:

Using procedures outlined in DealerCONNECT > TechCONNECT > Heating and Air Conditioning > Distribution > Housing, HVAC remove the HVAC distribution housing and install the revised assembly.



24-009-08 -2-

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
24-65-31-98	Install, revised HVAC distribution housing -WK (B)	3.6 Hrs.
24-65-31-97	Install, revised HVAC distribution housing -XK (B)	4.1 Hrs.

FAILURE CODE:

ZZ	Service Action	
----	----------------	--