



NUMBER: 19-006-04

GROUP: Steering

DATE: August 11, 2004

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

THIS BULLETIN IS BEING PROVIDED IN ADVANCE. DO NOT ORDER 05142893EA - HYDRAULIC SYSTEM / POWER STEERING FLUID, FOR THE EUROPEAN MARKET, UNTIL JANUARY 01, 2005.

SUBJECT:

New Hydraulic System / Power Steering Fluid

OVERVIEW:

This bulletin involves the introduction of a new hydraulic system / power steering fluid.

MODELS:

2005 (WK/WH) Grand Cherokee (All Markets)

DISCUSSION:

The 2005 Grand Cherokee requires the use of a new hydraulic system / power steering fluid. The new fluid is specially formulated to ensure long life of the vehicle hydraulic and power steering system.

The new fluid part number and name is 05142893AA - Hydraulic System / Power Steering Fluid (MS-10838). To address the European Union market requirements the part number is 05142893EA.

NOTE: Use only approved hydraulic system / power steering fluid (MS-10838) when servicing the 2005 Grand Cherokee power steering / hydraulic system.

DO NOT use automatic transmission fluid (ATF) or other types of power steering fluids when servicing or topping-off the 2005 Grand Cherokee power steering / hydraulic system. A white service label has been affixed to the 2005 Grand Cherokee power steering reservoir that contains similar instructions.

Damage to the power steering / hydraulic system can occur if the wrong hydraulic / power steering fluid is used.

POLICY:

Information Only.